



CAMPUS ENERGY 2016

The Changing
Landscape

February 8-12, 2016 | JW Marriott Austin Hotel | Austin, TX

USING INTELLIGENT PREDICTIVE CONDITION-BASED MONITORING FOR DETECTING & PREDICTING EQUIPMENT FAILURE AT THE UNIVERSITY OF TEXAS- AUSTIN

SPEAKER

ROBERTO DEL REAL

**UNIVERSITY OF TEXAS-AUSTIN, UTILITY &
ENERGY MANAGEMENT (UT-UEM)**

SUNIL WARKE

BNF TECHNOLOGY INC.

Contents

2

- Need at UT-UEM
- Technology Background
- Predictive Monitoring Solution
- Case Study
- Q & A

Need at UT-UEM


3

- University of Texas at Austin, Utility and Energy Management (UT-UEM) decided to adopt predictive maintenance based innovative solution which would help them in achieving their goal of providing un-interrupted and cost effective power supply for university campus.
- With the aim of this, UT-UEM has deployed condition based predictive monitoring solution called PHI.
- **Predictive monitoring solution-Value creation**
 - Improve stability of sensors
 - Improve stability of equipment
 - Improve availability and reliability of a plant

Technology Background

4


- In our plant, We have to monitor large number of data and equipment to identify abnormal conditions.



Technology Background

5

- How can you detect a failure early enough to provide time to plan and schedule with work without panic or reactivity?




Predictive Monitoring Solution

6


- The real-time predictive monitoring solution to identify equipment failure in advance
- What you can identify with help of Predictive Monitoring Solution?
 - Sensor failure
 - Potential equipment failure
 - Process failure
- Quick Recognition
 - Recognize anomalies for a plant health condition with health index number
 - Scrutinize abnormal equipment within a second
- Value Creation
 - Improve stability of sensors
 - Improve stability of equipment
 - Improve availability and reliability of a plant

Predictive Monitoring Solution

7



Predictive Monitoring Solution



Tag 1- S1_TT_SLFD (Temp) -TE-3420D seal oil feed temp

Tag-2 - S1_DWATT (Watt) - Generator Watt

Tag-3 - S1_TT_SSH(Temp) - Inlet Steam Temperature

Tag 4- S1_DF (Frequency) - Generator Frequency

Tag 5- S1_DV (Volts) - Generator Volts

Predictive Monitoring Solution

9

CTG 8 99.39%	CTG 10 7.89% (Stand-By)
BOILER 3 98.41%	BOILER 7 99.28%
BOILER 8 99.69%	BOILER 10 2.72% (Stand-By)
STG 7 31.39% (Stand-By)	STG 9 99.71%



Case Study


10

- **Plant :** UT-UEM
- **Issue :** CTG10 – Compressor Inlet Temperature Control – T2
- **Anomalies Observed :** HP Compressor Discharge Acoustic Dynamic Pressure was unstable and changing between 1.7 to 10.5 (PSID) during 21:45 to 22:00 hours on 27th April 2014. Large fluctuations in CTG10 speed and acoustic vibration levels were also observed. after that the CTG10 was stopped/tripped.
- **Action:** GE Aero was contacted to discuss reason for trip which was related to unit speed. According to GEK 112767 Volume I; the VSV system senses gas generator speed and compressor inlet temperature, and positions the VSV's. For any temperature and any speed, the VSV's take one position and remain in that position until the NGG or T2 changes. After the failure UT-UEM, corrected the control logic to control T2 at a steady temperature.

Time	Tag Name	Act Value	Exp. Value	Res. Value	Operating Value		EU Range		Unit
					Min	Max	Low	High	
2014-04-27 21:46:38	CTG10-HPCompressor-Discharge_Acoustic_Dynamic_Pr_PX36A_PT8090A	5.4	1.7	-3.8	1.634	2.9653	-1	10	PSID
	CTG10-HPCompressor-Discharge_Acoustic_Dynamic_Pr_PX36A_PT8090B	6.5	1.7	-4.8	1.680	3.0147	0	10	PSID

Case Study

11




Trend Details

Select All	Tagname	Description	Act Value	Exp Value	Res Value	Low	High	Unit	Remove
<input checked="" type="checkbox"/>	CTG10-HPCompressor-Discharge_Acoustic_Dynamic_Pr_PX36A_PT8090A	GT10 - PX36A - PT-8090A - Acoustic/Dynamic Pressure Sensor A	7.7	2.5	-5.2	-1	10	psid	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	CTG10-HPCompressor-Discharge_Acoustic_Dynamic_Pr_PX36B_PT8090B	GT10 - PX36B - PT-8090B - Acoustic/Dynamic Pressure Sensor B	7.3	2.5	-4.9	0	10	psid	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	CTG10-Gen-MW	GT10 Generator MW	27.2	27.1	-0.1	-1	40	MW	<input checked="" type="checkbox"/>

Case Study

12




Trend Details

Select All	Tagname	Description	Act Value	Exp Value	Res Value	Low	High	Unit	Remove
<input checked="" type="checkbox"/>	CTG10-HPCompressor-Discharge_Acoustic_Dynamic_Pr_PX36A_PT8090A	GT10 - PX36A - PT-8090A - Acoustic/Dynamic Pressure Sensor A	5.4	1.7	-3.8	-1	10	psid	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	CTG10-HPCompressor-Discharge_Acoustic_Dynamic_Pr_PX36B_PT8090B	GT10 - PX36B - PT-8090B - Acoustic/Dynamic Pressure Sensor B	6.5	1.7	-4.8	0	10	psid	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	CTG10-Gen-MW	GT10 Generator MW	23.6	23.5	-0.1	-1	40	MW	<input checked="" type="checkbox"/>

Case Study


13



Case Study

14


- The control diagram below depicts what was implemented to control T2 at a steady temperature.



Case Study

15


- The trend below depicts behavior before control scheme implementation



Case Study

16

- The trend below depicts behavior after control scheme implementation



Case Study

17

- The trend below depicts behavior after control scheme implementation - detailed



Case Study

18

- More stable T2 control advantages
 - Better CTG10 operation
 - Less stress in unit components
 - Better CS (source of cooling) performance
 - PHI continues to be looked at daily – UEM has hired an additional Engineer to manage this process
 - Q&A

Contact Information

19

Roberto del Real: Roberto.delreal@ausitn.utexas.edu

Sunil Warke: Sunil@bnftech.com



CAMPUS ENERGY 2016

The Changing
Landscape


February 8-12, 2016 | JW Marriott Austin Hotel | Austin, TX



Case Study


21

- System: Boiler 3 , FD Fan –Main Index Trend



Case Study

22



Trend Details

Select	Tag Name	Description	Low	High	Act Cursor1	Exp Cursor1	Res Cursor1	Act Cursor2	Exp Cursor2	Res Cursor2	Unit	...
<input checked="" type="checkbox"/>	B3-FDF-Fan_West_Torque	FD FAN WEST TORQUE	0	1000	1610.00	1360.92	-249.08	1657.00	1369.00	-288.00	FTLBS	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	B3-FDF-Fan_West_Current	WEST VFD FAN CURRENT	0	250	39.20	36.55	-2.65	39.00	36.50	-2.50	AMPS	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	B3-FDF-Fan_West_Frequency	WEST VFD FAN FREQ	0	100	21.84	21.57	-0.24	23.51	22.29	-1.22	HZ	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	B3-FDF-Fan_West_Output_Voltage	WEST VFD FAN OUTPUT VOLTAGE	0	500	172.00	168.43	-3.57	184.00	174.00	-10.00	VOLTS	<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>	B3-FDF-West_Speed	FD FAN WEST SPEED	0	2500	584.46	576.23	-8.23	628.14	596.48	-32.67	RPM	<input checked="" type="checkbox"/>

Case Study

23

- System: Boiler 3 , FD Fan
- It was observed that the quality of the main trend was dropped down to 25% on November 22, 2015 again about the same time after four days. This occurrence is observed on October 12, 2015 and December 14, 2015 after the fans were swapped.

Case Study

24

- FD-FAN speed and torque Actual-Expected Trend



Case Study

25

- A low health index was observed on boiler 3 and after analysis it was discovered that there were variation in west fan torque and the current as shown on actual-expected trend.
- This kind of behavior did alarm the system and was not observed in the plant historian database. According to the instrumentation team, there were two differential pressure transmitters were not in the same position hence the difference in readings.

Case Study

26


- FD-FAN Torque tag detail table for October 12, 2015

Time	Tag Name	Description	Actual Value	Expected Value	Operating Value (KSCFH)		EU Range (KSCFH)	
					Min	Max	Low	High
12/10/2015 7:26am	B3-FDF-Fan West_Torque	FD Fan west Torque	0	681	45	1686	0	1000

Case Study

27

Alarm Trend



Case Study

28

- There is a disparity between the instrument readings, ideally the readings from both instruments should be exactly the same. It was about 180 % more than the other one. The boiler was shut down and the meters were calibrated.
- After the calibration the difference in reading has improved remarkably, although the difference in reading is not equal, the improvement is tremendous. There is a need to calibrate instruments for further accurate reading.