### IN REHAB: REBUILDING UNIVERSITY OF FLORIDA'S UNDERGROUND INFRASTRUCTURE

#### **PRESENTED BY**

Jennifer Meisenhelder, PE Assistant Director, Facilities Operations UNIVERSITY OF FLORIDA



Vince Basilio, PE, CEM Steam Systems Engineer RMF ENGINEERING, Inc.

### **UNIVERSITY OF FLORIDA** AT A GLANCE

**TOP 10** Public University 50K+ Students

**75%** Live on-campus

The state's oldest university, traces its beginnings to 1853. Today, the university has **more than 55,000 students** and **16 colleges**. UF has a **2,000-acre campus** and **more than 1,000 buildings** on the main campus.



### **EXISTING CONDITIONS**



MECHANICAL MANHOLE: MH-3D3-9 SYSTEM CONDITION								CONDITION PHOTOS																
Manhole Co Neck Condi	er Condition: ondition: ition: Surface Tempera ent?	Obsv./ Perm Source:	Access Cove Spa Ladder Com Notes: 140 Depth: 0"/	alling: 🗹 dition: D deg F 18" and MH-3D3-	N/A Exposed Rebar Good 13	r: 🗆		Ru	sted and			or Plate	on		Loc	king South			Lookir	and North				
Pipe Hange Pipe Ancho	ors Condition:	Good Poor	Pipe Hange Pipe Anchor	rs Urgency:	N/A Immedi					6'	' 70S													
Service	Pipe Size (NPS		Pipe	Valve	Insulat		ller		Sacket	Ura		nsion Jo		Turre	Trap Size (in) (					1				
t Type 1 70S 2 PC	10 4				e A	Cond. Poor Poor	1 1	Type AL AL	Cond. Poor Poor	1 1	None	hannanananan	NA NA	None None	N/A N/A						2 2	- /		
3 70S 4 PC 5 70S	8 4 6			9	e ía	Poor Poor Poor	1 1 1	AL AL AL	Poor Poor Poor	1 1 1	SJ SJ SJ	Good Good Poor	NA 1	BiM None BiM	3/4				AL		2			
70S PC 70S	8 6 6			12		Poor Poor Poor	1 1 1	AL AL None	Poor Poor None	1 1 1	None	None None None	-	None None None	N/A						NA NA			
70C	3/4		The	11	à	Poor	1	N/A	None	1	None	None	NA	None	N/A				-	4	NA			
																				Jest -				
General:	3D3-8. This man	hole also serves ern portion of a	h isolation poin s as a low point	t with normal s for traps and a	MENTS / CON ervice from MH-3D ccommodates then . This manhole is v	3-12 to th rmal expa	ne south Insion f	rom the	north in t	he ste	am and o	ondensa	te syst	ems.	71	UTILI			TURE AS		IT			
Piping: Exp. Joints	6" 70S XJ is leak	packed, slip joir	ts with no base	anchors. The	6" 70S XJ is leaking nsion. Anchor failu	g no north Ire in adia	h side. J	Anchor   anhole.	plate on 6	" 70S	XJ has h	eaved off	concr	ete				Reliab ue Date: 2/2018	ility. Effici	ency. Integrit echanical Ma <u>MH-3D3-9</u>	anhole:	:		
																			I			<u> </u>	UF	

### **CAPITAL PLANNING** MAPPING




#### Legend

Steam MH Capital Planning Map Manhole (Water Intrusion) • 0.5 Manhole (Excess Heat) • Manhole (Mechanical Issues) 2 Manhole (Structural Issues) 2 Steam Meter M **Condensate** Piping Steam Piping Abandoned Piping Underground Enclosure Manhole temp

### **THERMAL IMAGE MAPPING** PROCESS




### **THERMAL HOT SPOT** MAPPING




Spot
Manhole
Steam Meter
Condensate Piping
Steam Piping
Abandoned Piping
Hot Spot Run
Hot Spot Cluster

Images added at each hot spot for clarity




### **UNIVERSITY OF FLORIDA** STEAM STANDARDS



### **UNIVERSITY OF FLORIDA** "TEAR OFF" PROJECTS

#### MH-3D2-23 - NORTH OF ANDERSON HALL



# MH-3D3-75 - DAUER HALL


#### SCOPE OF WORK

- · Provide insulation blankets on all major isolation valves.
- · Provide drain and warm-up at the 4" 70S valve.
- Replace all pressure gauges.
- Seal pipe penetrations that are leaking ground water into manhole.
- Insulate 70S and Steam trap piping that are currently un-insulated.
- Vent the manhole.
- Install steam driven sump pump and drainage.
- · Provide a rubber gasket for the manways to make them watertight
- · Provide a ladder extension for safe access into manhole.
- Replace rusted trap station and other affected piping after resolving


#### SCOPE OF WORK

- · Perform a thermal stress analysis to evaluate the effects of thermal expansion in this manhole.
- Seal the manhole structure at the precast concrete seams and the base of the manhole.
- · Test the water filling the manhole to determine if it is groundwater.
- Patch the cracks in the ceiling and remove built-up mineral deposits.
- Seal all pipe penetrations.
- Provide a sump pump for the manhole.
- · Provide a full-size drip-leg for the existing steam trap station.
- · Provide sparge pipes/flash arrestors to the pumped condensate piping.
- · Provide warm-ups at the steam isolation valves.
- Re-insulate the 10" 70S, 4" PC, and steam trap piping.
- · Provide insulation blankets for all isolation valves.
- Replace the simple supports on the steam trap piping.
- Replace both of the ladders.
- Provide proper venting for the manhole.
- Remove debris from the manhole.
- · Provide rubber gaskets for the manway lids to make the lids watertight.


### **TYPICAL MANHOLE** RECONSTRUCTION




MH-3D4-3 - ISOMETRIC VIEW - DEMOLITION SCALE



MH-3D4-3 - ISOMETRIC VIEW - NEW WORK SCALE:



MH-3D4-5 - ISOMETRIC VIEW - DEMOLITION BCALE:



MH-3D4-5 - ISOMETRIC VIEW - NEW WORK SCALE



### **UNIVERSITY OF FLORIDA** COMPLETED VAULT REPAIRS



### **T**II **T**II

### **UNIVERSITY OF FLORIDA** COMPLETED VAULT REPAIRS



### **UT**


### **UNIVERSITY OF FLORIDA** COMPLETED VAULT REPAIRS




### **UT**

### **DOCUMENTED RESULTS**


#### EXISTING



4 MH-3D4-61 - ISOMETRIC VIEW



NEW



(4) MH-3D4-61 - ISOMETRIC VIEW N



**T**II **T**II



#### EN HILL GRIFFIN STADIUM

## QUESTIONS?

